



GARY R. HERBERT
Governor

GREGORY S. BELL
Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

Division of Oil, Gas & Mining

MICHAEL R. STYLER
Executive Director

JOHN R. BAZA
Division Director

Inspection Report

Minerals Regulatory Program

May 9, 2012

Reviewed:

Mine Name: Quail 45	Permit Number: S/053/0066
Operator Name: Color Country Rock	Inspection Date: May 1, 2012
Inspector(s): Lynn Kunzler	Time: 4:00 pm
Other Participants: None	Mine Status: Reclaimed

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Re53/00visions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls, shafts,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

Purpose of Inspection:
Routine Inspection

Inspection Summary:

This site was reclaimed in 2007, and the BLM had subsequently closed their file. A search of DOGM files showed that we had not closed this file. The Division should have retired this site and closed the file a few years ago.

The site is stable and vegetation is quite similar to the surrounding vegetation. There were no signs of accelerated erosion. There was no trash on site. No apparent change from last inspection

Conclusions and Recommendations:

This site needs to be retired and the file closed.

Inspector's Signature

cc: Jeff Fawcett, Operator (fawcett_jeff@hotmail.com)

O:\M053-Washington\S0530066-Quail45\inspection\insp-05012012.doc